Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW2789/1

Work Order Type: Weatherization Audit Name: 12012NW2789

CLIENT INFORMATION

Client Name: Address:

Client ID: 12012NW2789

Alt. Client ID:

AGENCY INFORMATION

Agency: Northwest Tn. Economic Development Council Agency Phone: (731) 364-3228

Address: 231 South Wilson St. **Fax:** (731) 364-5029

Dresden, TN 38225-1312 Email Address:

Agency Contact: Woods, Max Work Phone: (731) 286-0332

Cell Phone: (731) 676-1414

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 12012NW2789
Alt. Client ID:

Work Order (Bid Form)
Work Order Name: WO/12012NW2789/1

Report Run On: 5/21/2010

DOE Weatherization Assistant Version 8.5.0 Page 1 of 5

		Itration Redctn			Componen	ts		1	Inspected
C	comment Foam p	olumbing at Kitchen and l	Bath						
	Pack/F	oam Head of Tub and sea	al access.	(Acces	ss located ur <i>Estimated</i>		en sink)	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Comment	H Tank Insulation Hot Water Heater			Componen				Inspected
C	Comment Electric	: Hot Water Heater			Estimated			Actual	
<i>C</i>	Comment Electric Material / Labor	: Hot Water Heater Description / Comment	Units	Qty			Qty		Inspected
<i>C</i>	Comment Electric	: Hot Water Heater	<i>Units</i> Each		Estimated		Qty	Actual	
# 1	Electric Electric Material / Labor Hot Water	: Hot Water Heater Description / Comment		Qty	Estimated		Qty	Actual	
# 1	Electric Electric Material / Labor Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1	Electric Electric Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1	Electric Electric Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1	Electric Electric Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1 1	Estimated			Actual	

Report Run On: 5/21/2010

Measure 3 DW	/H Pipe Insulation			Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail] [
			Moosur	e Sub Total:			Sub Total:	
			weasur	e Sub Total:		<u> </u>	Sub Total.	
Measure 4 Flo	oor Ins. R-19			Componen				Inspected
Comment		Units		Estimated		Otv	Actual	
	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19	<i>Units</i> SqFt	Qty 1026	•		Qty		Inspected Total
Comment # Material / Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt -		Qty	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation	Description / Comment Floor Insulation - Fiberglass Faced Batt -		Qty	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation	Description / Comment Floor Insulation - Fiberglass Faced Batt -		Qty	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation	Description / Comment Floor Insulation - Fiberglass Faced Batt -	SqFt	Qty 1026	Estimated			Actual	

Report Run On: 5/21/2010

Measure 5 CO N	Monitor is Needed			Componen	ts			Inspecte	
Comment									
				Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Health and Safety Items	CO monitor	Each	1						
2 Labor	Labor	Hour	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:									
	ours Dalief Dining Noos	Jad		Componen	40			Inspecto	
Measure 6 Pres	sureRelief Piping Need	ded		Componen	ts			Inspecte	
Measure 6 Pres	sureRelief Piping Need	ded		Componen Estimated			Actual	Inspecte	
Measure 6 Pres	sureRelief Piping Need Description / Comment	ded <i>Unit</i> s	Qty	-		Qty		Inspecte	
Measure 6 Pres Comment # Material / Labor			Qty 1	Estimated		Qty	Actual		
Measure 6 Pres Comment # Material / Labor 1 Health and Safety Items	Description / Comment	Units		Estimated		Qty	Actual		
Measure 6 Pres Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated		Qty	Actual		
Measure 6 Pres Comment # Material / Labor 1 Health and Safety Items	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated		Qty	Actual		
Measure 6 Pres Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated		Qty	Actual		
Measure 6 Pres Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Pressure relief piping	Units Each Hour	1	Estimated			Actual		
Measure 6 Pres Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Pressure relief piping	Units Each Hour	1	Estimated Unit Cost			Actual Unit Cost		
Measure 6 Pres Comment # Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment Pressure relief piping	Units Each Hour	1	Estimated Unit Cost			Actual Unit Cost		

	Measure 7	-	or Barrier Needed ement/Crawlspace)			Componen	its		ı	Inspected
C	Comment 10	26 sq.	ft. Ground Cover							
					Estimated			Actual		
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and S Items	Safety	Basement / crawlspace vapor barrier	Each	1					
2	Labor		Labor	Hour	1					
	Other Detail]		
L										
					Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:									
				Work Or	der Gra	nd Total:		Gran	d Total:	